

Lighting Audit Fixture Report

LighTec, Inc.

Reference

;
Prepared By: Richard Ellis
Version: 1.00

Reference Lighting Audit Fixture Report 3/29/2007

Zone	Location	Existing Condition	Action	Proposed Condition	EQty	PQty	Notes
typical							
1.00	Front Office Area Common	4L 34W-T12 Troffer EE/Std Mag	Remove & Install Fixture	NF 2x4 3L 30W BF L Pris Troff	24	24	
1.00	Front Office Area Common	65R30 Inc. Recessed Can	CFL Lamp Replacement	Retro 16W CFL Mini Spring	12	16	
1.20	Front Office Area Offices	4L 34W-T12 Troffer EE/Std Mag	Relamp, Reballast, & Clean	Retro 4L 30W 841 HP T8 BF L	12	12	
2.00	Warehouse	400W Metal Halide Highbay	New T5 Installation	NF 2X4 4 Lamp T5 OFO w/spec refl/Sensor & Cord	20	20	
2.00	Warehouse	No New System Required	Install Fixture Mounted Sensor	Fixture Installed Sensor	0	20	
4.00	Manufacturing	8' Ind HO Shaded EE/StdMag	1x8 Kit	Kit-1x8 2L Tand 32W w/ Wht Refl BF L	48	48	
5.00	Inspection Stations	1x4 2L 34W T12-EE/EEMag	Relamp, Reballast, & Clean	Retro 2L 30W HP T8 BF L	24	12	
6.00	Shipping & Receiving	8' Ind HO Shaded EE/StdMag	1x8 Kit	Kit-1X8-2LTand-30W HPT8 w/ Wht Refl BF L	12	12	
7.00	Shipping Office	2x4 4L 34W T12 EE/EEMag	Relamp, Reballast, & Clean	Retro 2L 32W HP T8 BF H	2	2	
typical					154	166	

Zone	Location	Existing Condition	Action	Proposed Condition	EQty	PQty	Notes
Grand Total:					154	166	
